

Exhibit B



UPPER FRAMING OF BALCONY IS COMING OFF OF THE REAR WALL



DECKING IS DETERIORATED



GUARDRAILS ARE 30" TALL

POSTS OF BALCONY ARE BEARING SOLELEY ON THE DECKING BOARDS OF THE EXISTING GROUND FLOOR DECK